

How to Get Your Slit Lamp to Glide Again

1. Rub a very (VERY) small amount of Vaseline in the center of the grey pad, starting in the center and working your way out. Wipe off all excess amounts.
2. Check the level of the table in both the vertical and horizontal directions. If the table is not level, [please fill out the Support Request form for additional assistance](#).

